



CEET

EMBRAER 170 CABIN EMERGENCY EVACUATION TRAINER

Location Lufthansa Aviation Training, Zurich

| Manufacturer | Embraer Brazil |
|--------------------|--|
| Door manufacturer | Latequere France |
| In service since | 2004 |
| Purpose | Operation of doors and exits in the normal and emergency |
| | modes. |
| | Passenger handling and crowd control training |
| | Evacuation procedure training |
| | Emergency procedure training |
| | Decompression procedures training |
| | Crew resource management training |
| Simulated aircraft | Embraer 170/175 (190 overwing on separate device) |
| Cabin layout | ■ 28 economy seats |
| | Forward & aft galley |
| | ■ Forward & aft lavatory |
| | 3 cabin crew member stations |
| Doors | ■ 2 main doors |
| | 2 service doors |
| | 1 door with power assist and adjustable forces (8, 28, 48, |
| | 68 kg) |



| Slides | 2 permanently inflated single lane slides |
|--------------------|--|
| | 1 slide in disengage-position |
| Features | Fasten seat belts & no smoking signs |
| | Pilot call & emergency call |
| | Public address (PA) and cabin interphone system |
| | 4 Passenger service units (oxygen mask units, reading lights |
| | and passenger call) |
| | Emergency & exit lights |
| | Air conditioned |
| | Lavatory handles heatable |
| | Lavatory call |
| Malfunctions | Door blocked (door 1L) |
| | Decompression |
| | Engine fire |
| | Lavatory fire (forward & aft) |
| | Door jammed with different values |
| | Power assist fail |
| Motion system | fixed base, original aircraft height |
| Visual system | Static, view cabin windows, sky only, |
| | Time of day (day & dusk) |
| | Outside fire |
| Smoke | Oil based, two zones (forward & aft cabin area) |
| Instructor station | 1 touch screen |
| | |